



## SAFETY RECOMMENDATION Nº 001-IIA/2018

Original publication information	
Title	Aircraft incident B 757-200, G-OOBA
Document Type	Safety Investigation Report
Document Reference N.º	01/INCID-A/IPIAAM/2018
Occurrence date	September 14, 2018
Publication date	November 10, 2022

Extract from the Safety Investigation Report of the Aircraft Incident B 757-200, G-OOBA

### Safety Recommendation Nº- 001-IIA-2018

As a result of the investigation, taking into account the chance of such an incident being repeated during the rainy season, it is recommended that operator TUI Airways Limited should promote the crew's adherence to protect the static and pitot probes after landing and while the aircraft remains on the ground;

### Entidade Recomendada

TUI Airways Limited

### Estado de Implementação

Ongoing