



## SAFETY RECOMMENDATION Nº 002-IIA/2018

Original publication information	
Title	Aircraft incident B 757-200, G-OOBA
Document Type	Safety Investigation Report
Document Reference N.º	01/INCID-A/IPIAAM/2018
Occurrence date	September 14, 2018
Publication date	November 10, 2022

Extract from the Safety Investigation Report of the Aircraft Incident B 757-200, G-OOBA

### Safety Recommendation Nº- 002-IIA-2018

TUI Airways Limited shall take safety actions subsequent to this incident and an in-house safety education magazine shall feature the incident in question as a case study, including points to note in the case of airspeed disagree, (airspeed unreliable) in order to prevent the recurrence of this incident;

### Entidade Recomendada

TUI Airways Limited

### Estado de Implementação

Ongoing